















Symbol	Dimensions In Millimeters		Symbol	Dimensions In Millimeters	
	Min	Max		Min	Max
A	2.20	2.40	E	5.95	6.25
B	0.95	1.25	e1	2.24	2.34
b	0.50	0.70	e2	4.43	4.73
b1	0.45	0.55	L1	9.42	9.55
D1	5.10	5.50	K	0.00	0.10



4  
kron

vede

CNC  
R  
E  
A  
T  
I  
V  
E  
D  
E  
V  
E  
L  
O  
P  
E  
M  
E  
N  
T